

Science Museum Library and Archives
Science Museum at Wroughton
Hackpen Lane
Wroughton
Swindon
SN4 9NS

Telephone: 01793 846222
Email: smlwroughton@sciencemuseum.ac.uk

CONC/A/1

C-series drawings

Compiled by John Coppen

CONC/A/1

Reference Code	Drawing No.	Title	Sheet No.	Date	Language	Box No.
CONC/A/1/001	C.00-0035	Croquis de Mise au Point N (Ensemble Meuble A Batteries)	None	07-Jul-71	French	3
CONC/A/1/002	C.00-0037	Croquis de Mise au Point N (Ensemble Meuble Electropompes)	None	12-Jul-71	French	3
CONC/A/1/003	C.00-0308	Croquis de Mise au Point N (Repercussions sur Cheminements Electriques de L'Installation des Meubles Generation HYD. De Secours)	None	13 Oct. 1971	French	3
CONC/A/1/004	C.00.9241	Alteration to Crew Members Seats.	Sht. 2 of 2	20 Oct. 1971	English	3
CONC/A/1/005	C02.5054	FWD Escape Chute; Assy. Tensator Spring Guard.	Sht. 1 of 2	1 Sept. 1970	English	3
CONC/A/1/006	C02.5055	Assy. Of Tensator Spring Guard at Inter. Esc. Chute.	Sht. 1 of 1	28 Aug. 1970	English	3
CONC/A/1/007	C02. 5059	Stowage for Portable Intake Covers	Sht. 1 of 1	6 Oct. 1970	English	3
CONC/A/1/008	C02.5062	Improvements to External A/C/ Surface	Sht. 1 of 1	20 Nov. 1970	English	3

CONC/A/1/009	C02.5062	Improvements to External A/C/ Surface	Sht. 1 of 2	26 Nov. 1970	English	3
CONC/A/1/010	C02.5065	Alteration to Brake Parachute Jettison Mechanism.	Sht. 1 of 1	12 Feb. 1971	English	3
CONC/A/1/011	C02.5066	First Class Locking Req.mts. FWD & Inter Chutes.	Sht. 1 of 1	14 Feb. 1971	English	3
CONC/A/1/012	C02.5067	Replacement of Desiccator Bottles	Sht. 1 of 1	23 Feb. 1971	English	3
CONC/A/1/013	C02.5068	Assy. of Hoist for Diverting Equipment	Sht. 1 of 3	24 Mar. 1971	English	3
CONC/A/1/014	C02.5068	Assy. of Hoist for Diverting Equipment	Sht. 2 of 3	20 Mar. 1971	English	3
CONC/A/1/015	C02.5068	Hoist for Diverting Equipment	Sht. 3 of 3	11 Mar. 1971	English	3
CONC/A/1/016	C02.5069	Assy of Hoist , Lateral Restraint.	Sht. 1 of 1	27 May 1071	English	3
CONC/A/1/017	C03.5020	Alt. to Bracket Assy Air-Brake Jack.	Sht. 1 of 1	9 Feb. 1971	English	3
CONC/A/1/018	C11.0356	Carenage de Fermeture Autour Ferrure Attache Nacelle. Cover Fairing Around Nacelle Attmt. Fitting.	Sht. 1 of 1	16 Feb. 1971	French	3
CONC/A/1/019	C11.0357	Carenage Ferrure	Sht. 1 of 1	26 Feb.	French	3

		Attache Nacelle. L57. N21. ©		1970		
CONC/A/1/020	C11.0357	Carenage Ferrure Attache Nacelle. L57. N21. (B)	Sht. 1 of 1	26 Feb. 1970	French	3
CONC/A/1/021	C11.5418	Blanking of Holes-Cone Statics. All Intakes.	Sht. 1 of 1	24 Sept. 1970	English	3
CONC/A/1/022	C11.5423	Mod to Banjo Fittings Cone Statics- All Intakes.	Sht. 1 of 1	29 Sept. 1970	English	3
CONC/A/1/023	C11.5424	Mod to Special Plug Cone Statics- All Intakes.	Sht. 1 of 1	29 Sept. 1970	English	3
CONC/A/1/024	C11.5431	Pipe Tie	Sht. 1 of 1	24 Mar. 1971	English	3
CONC/A/1/025	C11.5432	Pipe Clamp (5AY. 2 & 4)	Sht. 1 of 1	24- May-71	English	3
CONC/A/1/026	C11.5433	G.A. Boundary?	Sht. 1 of 1	23- Jul-71	English	3
CONC/A/1/027	C11.5434	Joint Entre Voilure et Nacelle. Joint Between Wing & Nacelle.	Sht. 1 of 1	10 Mar. 1971	French	3
CONC/A/1/028	C11.5435/1	Nacelles Couvercle. (Cover)	Sht. 1 of 1	10 Mar. 1971	French	3
CONC/A/1/029	C11.5435/2	Nacelles Couvercle. (Cover)	Sht. 1 of 1	10 Mar. 1971	French	3
CONC/A/1/030	C1.5437	Element Arriere de	None	None	French	3

Joint (Seal
Aft Item)

CONC/A/1/031	C11.5438	Conduit pour Cheminement Electrique dans Nacelle. (Conduit for Electrical run in Nacelle.)	None	23 Feb. 1971	French	3
CONC/A/1/032	C11.5445	Cone Statique (Static Cone)	None	2 Mar. 1971	French	3
CONC/A/1/033	C11.5448	Altn. To Valve Fixing Bolts - Charge Air Bleed- Motors 2, 3 & 4.	Sht. 1 of 1	22 Mar. 1971	English	3
CONC/A/1/034	C11.5451	Installation of Panels. Bays 3 & 4.	Sht. 1 of 7	16 Mar. 1972	English	3
CONC/A/1/035	C11.5451	Installation of Panels. Bays 3 & 4.	Sht. 2 of 7	16 Mar. 1972	English	3
CONC/A/1/036	C11.5451	Installation of Panels. Bays 3 & 4.	Sht. 3 of 7	16 Mar. 1972	English	3
CONC/A/1/037	C11.5451	Installation of Panels. Bays 3 & 4.	Sht. 4 of 7	16 Mar. 1972	English	3
CONC/A/1/038	C11.5451	Installation of Panels. Bays 3 & 4.	Sht. 5 of 7	22 Mar. 1972	English	3
CONC/A/1/039	C11.5451	Installation of Panels. Bays 3 & 4.	Sht. 6 of 7	23 Mar. 1972	English	3
CONC/A/1/040	C11.5451	Installation of Panels. Bays 3 & 4.	Sht. 7 of 7	24 Mar. 1972	English	3
CONC/A/1/041	C11.5452	Panel - Bay 3.	Sht. 1 of 3.	22 Mar. 1972	English	3

CONC/A/1/042	C11.5452	Panel - Bay 3.	Sht. 2 of 3.	16 Mar. 1972	English	3
CONC/A/1/043	C11.5452	Panel - Bay 3.	Sht. 3 of 3.	16 Mar. 1972	English	3
CONC/A/1/044	C11.5453	Modification to Bottom Panel -1/B Diffuser - R.H.	Sht. 1 of 1	16 Mar. 1972	English	3
CONC/A/1/045	C11.5454	Door Surround Structure	Sht. 1	17 Mar. 1972	English	3
CONC/A/1/046	C11.5455	G.A. of Modifications to Intakes 3 & 4 Structure.	Sht. 1 of 1	24 Mar. 1972	English	3
CONC/A/1/047	C11.5456	Modification to Bottom Panel -O/B Diffuser - R.H.	Sht. 1 of 1	22 Mar. 1972	English	3
CONC/A/1/048	C11.5457	Panel - Bay 4.	Sht. 1 of 2	22 Mar. 1972	English	3
CONC/A/1/049	C11.5457	Panel - Bay 4.	Sht. 2 of 2	22 Mar. 1972	English	3
CONC/A/1/050	C11.5460	Skin Riveting - Bay 4.	None	20- Apr-72	English	3
CONC/A/1/051	C11.5461	Assy. Of Door & Fairing	Sht. 1 of 1	11 Apr. 1972	English	3
CONC/A/1/052	C11.5462	Door Surround Structure - Bay 4.	Sht. 1.	17 Mar. 1972	English	3
CONC/A/1/053	C11.5463	Skin Riveting - Bay 3.	Sht. 1 of 1	12- Apr-72	English	3

CONC/A/1/054	C11.5464	Door (Detail, Sub Assy.)	Sht. 1 of 1	11 Apr. 1972	English	3
CONC/A/1/055	C11.5465	Fairing (Detail Assy)	Sht. 1 of 1	11 Apr. 1972	English	3
CONC/A/1/056	C11.5466	Details of Flap. Pivot Block, Saddle Clips etc.	Sht. 1 of 1	11 Apr. 1972	English	3
CONC/A/1/057	C11.5467	Ferrure dans Panneau Interne. Moteur 1.	Sht. 1 of 1	None	French	3
CONC/A/1/058	C11.5468	Decoupe dans Panneau Interne. Moteur 1.	Sht. 1 of 1	None	French	3
CONC/A/1/059	C11.5470	Decoupage Panneau Inf. Montage Nouveau Panneau (2)	Sht. 1 of 1	05- Apr-72	French	4
CONC/A/1/060	C11.5471	Decoupage dans Pan. neau Inf. Monteur 1.	Sht. 1 of 1	06- Apr-72	French	4
CONC/A/1/061	C11.5472	Montage Panneau Interne Mot. 2	Sht. 1 of 2	None	French	4
CONC/A/1/062	C11.5472	Montage Panneau Moteur 2.	Sht. 2 of 2	10- May-72	French	4
CONC/A/1/063	C11.5473	Decoupe dans Panneau Interne. Moteur 2.	Sht. 1 of 1	12- Apr-72	French	4
CONC/A/1/064	C11.5474	Montage Panneau Moteur 1.	Sht. 2 of 2	None	French	4

CONC/A/1/065	C11.5475	Raidisseurs Entre. Intrados. Extrados Entrée D'Air	Sht. 1 of 1	None	French	4
CONC/A/1/066	C11. 5481	Diaphragm	Sht. 1 of 1	11- Apr-72	English	4
CONC/A/1/067	C11. 5482	Diaphragm	Sht. 1 of 1	11- Apr-72	English	4
CONC/A/1/068	C11. 5483	Diaphragm	Sht. 1 of 1	11- Apr-72	English	4
CONC/A/1/069	C11. 5484	Diaphragm	Sht. 1 of 1	11- Apr-72	English	4
CONC/A/1/070	C11. 5485	Diaphragm	Sht. 1 of 1	13- Apr-72	English	4
CONC/A/1/071	C11. 5486	Diaphragm	Sht. 1 of 1	13- Apr-72	English	4
CONC/A/1/072	C11. 5487	Diaphragm	Sht. 1 of 1	12- Apr-72	English	4
CONC/A/1/073	C11. 5488	Diaphragm	Sht. 1 of 1	12- Apr-72	English	4
CONC/A/1/074	C11. 5489	Cleat	None	13- Apr-72	English	4
CONC/A/1/075	C11. 5499	Reinforcing	None	14- Apr-72	English	4
CONC/A/1/076	C11.5500	Landing Door	None	16- Apr-72	English	4
CONC/A/1/077	C11.7000	Landing Door	None	16- Apr-72	English	4
CONC/A/1/078	C11.7008	Montage Raidisseur Entrée D'Air. 1.	Sht. 1 of 1	None	French	4
CONC/A/1/079	C11.7014	Attachment Brkt.	None	26- Jun-72	English	4

CONC/A/1/080	C11. 7045	Alterations to Ramp Rigging Instns.	Sht. 1 of 1	27 Oct. 1972	English	4
CONC/A/1/081	C11. 7045	Alterations to Ramp Rigging Instns.	None	22 Nov. 1972	English	4
CONC/A/1/082	C11. 7046	Altn. To Ramp Link Attachment Housing.	None	17 Nov. 1972	English	4
CONC/A/1/083	C11. 7047	Altn. To Ramp Link Attachment Assy. Key.	None	1 Dec. 1972	English	4
CONC/A/1/084	C11. 9035	Banjo Fitting (Cone Statics)	None	6 Sept. 1970	English	4
CONC/A/1/085	C12.0010	Assy. Of Duct Charge Air Bleed	None	12- Jun-67	French	4
CONC/A/1/086	C12.5045	To Position nearer the Roof Power Switching Unit.	Sht. 1 of 1	15 Mar. 1971	English	4
CONC/A/1/087	C12.5046	Minor Alts. Associated with Ramp Transmission Mod All Intakes.	None	23 Mar. 1971	English	4
CONC/A/1/088	C12.5047	Altn. to Duct-Charge Air Bleed Bays 2-3-4.	Sht. 1 of 1	23 Mar. 1971	English	4
CONC/A/1/089	C12.5049	Altn. to Bracket for Cone Statics (All intakes)	Sht. 1 of 1	24 Mar. 1971	English	4
CONC/A/1/090	C12.5050	Ramp Transmission	None	05- Apr-71	English	4

Mod D 0534.
A/C 001
Variations.

CONC/A/1/091	C12.5051	Minor Alts. To Walking Beam-Bays 1 & 3.	None	27-May-71	English	4
CONC/A/1/092	C12.5054	Application of Viton to 'A' Panel Heat Shields. All Bays.	None	12 Aug. 1971	English	4
CONC/A/1/093	C12.5055	Rubbing Strip Plenum Chamber- All Engine Bays.	Sht. 1 of 1	14 Aug. 1971	English	4
CONC/A/1/094	C12.5056	Change of Matl. -Drip Tray Support Straps - All Intakes.	None	19 Aug. 1971	English	4
CONC/A/1/095	C12. 5059	Assy. of Safety Clips, Fuel Heater O/B Vent, Bays 2 & 4.	None	09-Jun-72	English	4
CONC/A/1/096	C19.5022	Assy. Of Replacement Ramp Att't. Fitting Assy.	Sht. 1 of 1	30 Jan. 1971	English	4
CONC/A/1/097	C19.5023	Detail of Fitting for Deffuser Panel (Intake 4)	None	31 Jan. 1971	English	4
CONC/A/1/098	C19. 5025	Bottom Outb'd. Skin Panel (Intake 4)	Sht. 1 of 1	1 Feb. 1971	English	4
CONC/A/1/099	C19. 5026	Centre Boom Frame 97.32 (Intake 4)	Sht. 1 of 1	2 Feb. 1971	English	4
CONC/A/1/100	C19.5029	Repair to Rib at Stn. XMF	Sht. 1 of 1	3 Feb. 1971	English	4

101.5879.

CONC/A/1/101	C19.5030	Tee Piece.	Sht. 1 of 1	9 Feb. 1971	English	4
CONC/A/1/102	C19.5031	Patch Plate	Sht. 1 of 1	3 Feb. 1971	English	4
CONC/A/1/103	C19.5032	Repair of External Skin & Frames. Assy. Of New Centre Booms- Intakes 3 & 4.	Sht. 1 of 4	8 Feb. 1971	English	4
CONC/A/1/104	C19.5032	Repair of External Skin & Frames. Assy. Of New Centre Booms- Intakes 3 & 4.	Sht. 2 of 4	4 Feb. 1971	English	4
CONC/A/1/105	C19.5032	Repair of External Skin & Frames. Assy. Of New Centre Booms- Intakes 3 & 4.	Sht. 3 of 4	3 Feb. 1971	English	4
CONC/A/1/106	C19.5032	Repair of External Skin & Frames. Assy. Of New Centre Booms- Intakes 3 & 4.	Sht. 4 of 4	10 Feb. 1971	English	4
CONC/A/1/107	C19.5033	Centre Boom Frame 93.32 (Intake 4)	Sht. 1 of 1	3 Feb. 1971	English	4
CONC/A/1/108	C19.5034	G.A. of Repairs to No. 4, Intake.	Sht. 1 of 1	3 Feb. 1971	English	4
CONC/A/1/109	C19.5035	Repair to Sidewall (Intake 4)	Sht. 1 of 1	8 Feb. 1971	English	4
CONC/A/1/110	C19.5037	Bracket	Sht. 1 of 1	9 Feb. 1971	English	4

CONC/A/1/111	C19.5027	Patch Plate	Sht. 1 of 1	4 Feb. 1971	English	4
CONC/A/1/112	C19.5038	Bracket	Sht. 1 of 1	9 Feb. 1971	English	4
CONC/A/1/113	C19.5039	Vis & Entretoise pour Reparation Nacelles.	None	23 Feb. 1971	French	4
CONC/A/1/114	C19.5040	Repair to Sidewall Spar 72 - All Eng. Bays.	Sht. 1 of 1	4 Mar. 1971	English	4
CONC/A/1/115	C19.5041	Altns. To Fairings.	Sht. 1 of 1	8 Mar. 1971	English	4
CONC/A/1/116	C19.5042	Alterations to Intake Ramp Mechanism.	Sht. 1 of 1	1 Mar. 1971	English	4
CONC/A/1/117	C19.5043	Alterations to Intake Ramp Mechanism. Bay 2.	None	1 Mar. 1971	English	4
CONC/A/1/118	C19.5044	Repair to Cracked Outer Fairing.	None	Apr-71	English	4
CONC/A/1/119	C19.5045	Support Brkts.	None	5 Mar. 1971	English	4
CONC/A/1/120	C19.5046	Repair to Sidewall Panel. Bays 2 & 3.	Sht. 1 of 1	1 Mar. 1971	English	4
CONC/A/1/121	C19.5047	Repair to Drip Tray Bay 4.	Sht. 1 of 1	23 Mar. 1971	English	4
CONC/A/1/122	C19.5048	Inner Skin Corner Fillet. Bottom Outbd. Sidewall Int. 3 & 4.	None	02- Apr-71	English	4

CONC/A/1/123	C19. 5036	Repair to Roof (Intake No. 4.)	Sht. 1 of 1	10 Feb. 1971	English	4
CONC/A/1/124	C19.5049	Repair to Fwd. Eng. Door Inn. Skin (L.H. I/B).	Sht. 1 of 1	30 Aug. 1971	English	4
CONC/A/1/125	C19.5051	Repair to Sidewall Spar 71 - 72. All Bays.	Sht. 1 of 9	19- Jun-72	English	4
CONC/A/1/126	C19.5051	Repair to Sidewall Spar 71 - 72. All Bays.	Sht. 2 of 9	19- Jun-72	English	4
CONC/A/1/127	C19.5051	Repair to Sidewall Spar 71 - 72. All Bays.	Sht. 3 of 9	19- Jun-72	English	4
CONC/A/1/128	C19.5051	Repair to Sidewall Spar 71 - 72. All Bays.	Sht. 4 of 9	20- Jun-72	English	4
CONC/A/1/129	C19.5051	Repair to Sidewall Spar 71 - 72. All Bays.	Sht. 5 of 9	19- Jun-72	English	4
CONC/A/1/130	C19.5051	Repair to Sidewall Spar 71 - 72. All Bays.	Sht. 6 of 9	20- Jun-72	English	4
CONC/A/1/131	C19.5051	Repair to Sidewall Spar 71 - 72. All Bays.	Sht. 7 of 9	19- Jun-72	English	4
CONC/A/1/132	C19.5051	Repair to Sidewall Spar 71 - 72. All Bays.	Sht. 8 of 9	19- Jun-72	English	4
CONC/A/1/133	C19.5052	Reinforcing Bays 1 & 4	Sht. 1 of 2	19- Jun-72	English	4

		Top.				
CONC/A/1/134	C19.5052	Reinforcing Bays 1 & 4 Top.	Sht. 2 of 2	19- Jun-72	English	4
CONC/A/1/135	C19.5053	Reinforcing Bays 1 & 4 Bottom.	Sht. 1 of 3	19- Jun-72	English	4
CONC/A/1/136	C19.5053	Reinforcing Bays 1 & 4 Bottom.	Sht. 2 of 3	19- Jun-72	English	4
CONC/A/1/137	C19.5053	Reinforcing Bays 1 & 4 Bottom.	Sht. 3 of 3	29- Jun-72	English	4
CONC/A/1/138	C19.5054	Reinforcing Bays 2 & 3 Top.	Sht. 1 of 2	19- Jun-72	English	4
CONC/A/1/139	C19.5054	Reinforcing Bays 2 & 3 Top.	Sht. 2 of 2	19- Jun-72	English	4
CONC/A/1/140	C21.1939	Groupe Hydraulique Secours.	None	31 Jan. 1971	French	5
CONC/A/1/141	C21.1941	Installation D'un Micro Ventilateur dans Meuble a Batteries 11 CAB.4.	None	18 Nov. 1971	French	5
CONC/A/1/142	C22.584	Verin Contrefiche de Béquille Arriere.	None	None	French	5
CONC/A/1/143	C31.0118	Fuselage TR 20 Commercial. Emboutl sur Fond Cabine.	None	29- Jul-71	French	5
CONC/A/1/144	C31.5009	Alt. to Mod. To Window Blinds - Flight Deck.	Sht. 1 of 1	4 Mar. 1971	English	5

CONC/A/1/145	C31.5010	Mod. To Window Blinds - Flight Deck.	Sht. 1 of 1	19 Mar. 1971	English	5
CONC/A/1/146	C42.0510	Hydraulique. Installation des Filtres Bleus au Couple 71.	None	14 Feb. 1969	French	5
CONC/A/1/147	C42.0587	Fuselage TR 20 Hydraulique. Traversees Etanches C72.	None	23- Jul-71	French	5
CONC/A/1/148	C42.0588	ENS Generation Hydraulique de Secours.	None	30 Aug. 1971	French	5
CONC/A/1/149	C42.0590	Generation Hydraulique de Secours Entre C72. ET C76.	None	23 Aug. 1971	French	5
CONC/A/1/150	C42. 0591	Hydraulique Cavalier, Troncon 20.	None	25 Aug. 1971	French	5
CONC/A/1/151	C42.0592	Troncon 20, Hydraulique. Support de Prises Hydrauliques C.72 cote Droit Essai de Decrochage.	None	30 Aug. 1971	French	5
CONC/A/1/152	C42.0593	Troncon 20, Ferrure Support de Prises Hydrauliques C.72 . L23 cote Droit Essai de Decrochage.	None	30 Aug. 1971	French	5
CONC/A/1/153	C42.0594	Troncon 20, Ferrure Support de	None	30 Aug. 1971	French	5

Prises
Hydrauliques
C.72 . L24
cote Droit
Essai de
Decrochage.

CONC/A/1/154	C42.0595	Troncon 20, Gouttieres Hydrauliques sur Meuble Electropompe.	None	14 Oct. 1971	French	5
CONC/A/1/155	C42.5010	Troncon 20, Montage Clapet de Securite Degazeur Baches.	None	2 Mar. 1971	French	5
CONC/A/1/156	C42.5712	Generation Hydraulique Secours.	Sht. 1 of 2	31 Jan. 1973	French	5
CONC/A/1/157	C42.5712	Generation Hydraulique Secours.	Sht. 2 of 2	10 Mar. 1973	French	5
CONC/A/1/158	C42.5713	Generation Hydraulique Secours Rapide. Montage Prises a Demontage. Support CA. 72 Cote Droit.	None	7 Mar. 1973	French	5
CONC/A/1/159	C52.0528	Ventilation Meuble Batteries.	None	23 Sept. 1971	French	5
CONC/A/1/160	C52.5022	Desembuage Hublots Montage Filtres.	None	29 Dec. 1971	French	5
CONC/A/1/161	C72.0626	Modification Chapeau Support Boutons Poussoir C.de. Trim	None	3 Dec. 1970	French	5

Electrique.

CONC/A/1/162	C72.5066	Alt. To Bond g. Clip on Pitch Spring Pot. On Artif'l. Feel Unit	None	2 Feb. 71	English	5
CONC/A/1/163	C98.0821	Oxygene Circuit E.V. Fuselage TR. 42.	None	15 Jan. 1972	French	5
CONC/A/1/164	C98.5808	Generation Hydraulique Secours	None	24 Nov. 1973	French	5
CONC/A/1/165	C98.7167	Spacer (Static Pressure Plotting)	None	None	English	5
CONC/A/1/166	C98.7711	Radiation Detector Support.	None	17- May-71	English	5
CONC/A/1/167	C72.5069	Mod. To Hydraulic Damper (Escape Chutes)	None	14 Oct. 1971	English	5